CERTIFICATE OF COMPLIANCE

CERTIFICATE No.: B2PT5086-001

1. U.S. IMPORTER OR DOMESTIC MANUFACTURER:

2A. PLACE OF FINAL MANUFACTURE:

Bisque ImportsQuality Assurance Representative

1 Belmont Avenue Belmont, NC 28012 1-888-568-5991 quality@bisqueimports.com Jiangmen, Guangdong China

*Address updated on October 25, 2013

2B. DATE OF MANUFACTURE (MONTH/YEAR):

June 2012

3A. PRODUCT IDENTIFICATION:

Brand: Mosaic Glass Tile

3B. LABORATORY REPORTS SUPPORTING CONFORMANCE:

B2PT5086-1

December 7, 2012

4. CITATION FOR CONFORMANCE:

The product referenced in 3A was tested to specifications and test methods found in the laboratory reports referenced in 3B wherein the product is said to conform to the following:

◯ CPSIA Section 101 – *Lead In Substrate* (100PPM)

⊠ CPSIA Section 108- *Phthalates Content*

5A. PRODUCT TESTING LOCATION:

Arlington, Texas U.S.A

5B. PRODUCT TESTING DATE:

SEE 3B

6. RECORDS OF TESTING RESULTS MAINTAINED BY:

Bisque Imports

Quality Assurance Representative 1 Belmont Avenue Belmont, NC 28012 1-888-568-5991

quality@bisqueimports.com

7. THIRD-PARTY LABORATORY CERTIFYING TESTING:

Armstrong Forensic Laboratory, Inc.

330 Loch'n Green Trail Arlington, Texas U.S.A. 76012

800-644-4175

www.AFLab.com

PJLA Accreditation No.: 64631

THIS CERTIFICATE OF COMPLIANCE WAS ISSUED BY:

THIS CERTIFICATE OF COMPLIANCE WAS PROVIDED TO:

Armstrong Forensic Laboratory, Inc.

*Address updated on October 25, 2013

330 Loch'n Green Trail

Arlington, Texas U.S.A. 76012

800-644-4175

www.AFLab.com

PJLA Accreditation No.: 64631

Bisque Imports

Quality Assurance Representative

1 Belmont Avenue Belmont, NC 28012

1-888-568-5991

quality@bisqueimports.com

*Address updated on October 25, 2013

This Certificate of Compliance meets the requirements established by Section 14(g) of the Consumer Product Safety Act, 15 U.S.C. § 2063(g). This Certificate of Compliance relates only to the products submitted to and tested by the certifying laboratory identified in Item 7.

The information for Items 2 and 3 was provided by the importer or manufacturer identified in Item 1.

CERTIFICATE OF COMPLIANCE

CERTIFICATE No.: B3PT0118-001

1. U.S. IMPORTER OR DOMESTIC MANUFACTURER:

2A. PLACE OF FINAL MANUFACTURE:

Bisque Imports

Quality Assurance Representative 1 Belmont Avenue Belmont, NC 28012 1-888-568-5991 quality@bisqueimports.com Jiangmen, Guangdong China

*Address updated on October 25, 2013

2B. DATE OF MANUFACTURE (MONTH/YEAR):

October 2012

3A. PRODUCT IDENTIFICATION:

Brand: Purple Glass Mosaic Glitter Tile

3B. LABORATORY REPORTS SUPPORTING CONFORMANCE:

B3PT0118-1

January 17, 2013

4. CITATION FOR CONFORMANCE:

The product referenced in 3A was tested to specifications and test methods found in the laboratory reports referenced in 3B wherein the product is said to conform to the following:

◯ CPSIA Section 101 – *Lead In Substrate* (100PPM)

⊠ CPSIA Section 108- *Phthalates Content*

5A. PRODUCT TESTING LOCATION: **Arlington, Texas U.S.A**

5B. PRODUCT TESTING DATE:

SEE 3B

6. RECORDS OF TESTING RESULTS MAINTAINED BY:

Bisque Imports

Quality Assurance Representative 1 Belmont Avenue Belmont, NC 28012 1-888-568-5991

quality@bisqueimports.com

*Address updated on October 25, 2013

7. THIRD-PARTY LABORATORY CERTIFYING TESTING:

Armstrong Forensic Laboratory, Inc.

330 Loch'n Green Trail Arlington, Texas U.S.A. 76012

800-644-4175

www.AFLab.com

PJLA Accreditation No.: 64631

THIS CERTIFICATE OF COMPLIANCE WAS ISSUED BY:

THIS CERTIFICATE OF COMPLIANCE WAS PROVIDED TO:

Armstrong Forensic Laboratory, Inc.

330 Loch'n Green Trail

Arlington, Texas U.S.A. 76012

800-644-4175

www.AFLab.com

PJLA Accreditation No.: 64631

Bisque Imports

Quality Assurance Representative

1 Belmont Avenue

Belmont, NC 28012 1-888-568-5991

quality@bisqueimports.com

*Address updated on October 25, 2013

This Certificate of Compliance meets the requirements established by Section 14(g) of the Consumer Product Safety Act, 15 U.S.C. § 2063(g). This Certificate of Compliance relates only to the products submitted to and tested by the certifying laboratory identified in Item 7.

The information for Items 2 and 3 was provided by the importer or manufacturer identified in Item 1.